

Linked vehicles

Description	Model year	TecDoc type no.	kW	HP	cc	Body type
VOLVO S60 II (134) 2.0 Polestar AWD Lambda Sensor Diagnostic Probe	06.2015 - 05.2018	120525	270	367	1969	Saloon
VOLVO S60 II (134) T3 Lambda Sensor Diagnostic Probe	03.2015 - 05.2018	113269	112	152	1969	Saloon
VOLVO S60 II (134) T4 Lambda Sensor Diagnostic Probe	03.2015 - 05.2018	114198	140	190	1969	Saloon
VOLVO S60 II Cross Country (134) T5 AWD Lambda Sensor Diagnostic Probe	06.2016 - 12.2018	147926	180	245	1969	Saloon
VOLVO S60 II Cross Country (134) T5 AWD Lambda Sensor Diagnostic Probe	06.2016 - 12.2018	147926	180	245	1969	Saloon
VOLVO S60 II Cross Country (134) T5 Drive-E Polestar AWD Lambda Sensor Diagnostic Probe	06.2016 - 05.2018	138826	186	253	1969	Saloon
VOLVO S60 II Cross Country (134) T5 Drive-E Polestar AWD Lambda Sensor Diagnostic Probe	06.2016 - 05.2018	138826	186	253	1969	Saloon
VOLVO S80 II (124) 2.0 Drive- E Lambda Sensor Diagnostic Probe	12.2014 - 12.2016	109981	180	245	1969	Saloon
VOLVO S80 II (124) T5 Lambda Sensor Diagnostic Probe	01.2014 - 12.2016	120516	162	220	1969	Saloon
VOLVO S80 II (124) T5 Lambda Sensor Diagnostic Probe	09.2013 - 05.2014	100519	180	245	1969	Saloon
VOLVO V40 Cross Country (526) T3 Lambda Sensor Diagnostic Probe	04.2015 - 08.2019	147902	112	152	1498	Hatchback
VOLVO V40 Cross Country (526) T4 Lambda Sensor Diagnostic Probe	08.2015 - 08.2019	147904	140	190	1969	Hatchback
VOLVO V40 Cross Country (526) T5 AWD Lambda Sensor Diagnostic Probe	05.2014 - 08.2019	108766	180	245	1969	Hatchback
VOLVO V40 Cross Country (526) T5 AWD Lambda Sensor Diagnostic Probe Lambda Sensor Diagnostic Probe Lambda Sensor Diagnostic Probe	05.2014 - 08.2019	108766	180	245	1969	Hatchback
VOLVO V40 Cross Country (526) T5 AWD Lambda Sensor Diagnostic Probe Lambda Sensor Diagnostic Probe Lambda Sensor Diagnostic Probe	05.2014 - 08.2019	108766	180	245	1969	Hatchback
VOLVO V40 Cross Country (526) T5 AWD Lambda Sensor Diagnostic Probe	05.2014 - 08.2019	108766	180	245	1969	Hatchback
VOLVO V40 Hatchback (525) T2 Lambda Sensor Diagnostic Probe Lambda Sensor Diagnostic Probe Lambda Sensor Diagnostic Probe	02.2015 - 08.2019	111884	90	122	1498	Hatchback
VOLVO V40 Hatchback (525) T2 Lambda Sensor Diagnostic Probe	02.2015 - 08.2019	111884	90	122	1498	Hatchback
VOLVO V40 Hatchback (525) T2 Lambda Sensor Diagnostic Probe	02.2015 - 08.2019	111857	90	122	1969	Hatchback
VOLVO V40 Hatchback (525) T2 Lambda Sensor Diagnostic Probe Lambda Sensor Diagnostic Probe Lambda Sensor Diagnostic Probe	02.2015 - 08.2019	111857	90	122	1969	Hatchback
VOLVO V40 Hatchback (525) T3 Lambda Sensor Diagnostic Probe	02.2015 - 08.2019	112556	112	152	1498	Hatchback
VOLVO V40 Hatchback (525) T3 Lambda Sensor Diagnostic Probe Lambda Sensor Diagnostic Probe Lambda Sensor Diagnostic Probe	02.2015 - 08.2019	112556	112	152	1498	Hatchback
VOLVO V40 Hatchback (525) T3 Lambda Sensor Diagnostic Probe	02.2015 - 08.2019	111858	112	152	1969	Hatchback
VOLVO V40 Hatchback (525) T3 Lambda Sensor Diagnostic Probe Lambda Sensor Diagnostic Probe Lambda Sensor Diagnostic Probe	02.2015 - 08.2019	111858	112	152	1969	Hatchback
VOLVO V40 Hatchback (525) T4 Lambda Sensor Diagnostic Probe	08.2015 - 08.2019	116592	140	190	1969	Hatchback

Description	Model year	TecDoc type no.	kW	HP	cc	Body type
VOLVO V40 Hatchback (525) T5 Lambda Sensor Diagnostic Probe Lambda Sensor Diagnostic Probe Lambda Sensor Diagnostic Probe	05.2014 - 08.2019	106280	180	245	1969	Hatchback
VOLVO V40 Hatchback (525) T5 Lambda Sensor Diagnostic Probe	05.2014 - 08.2019	106280	180	245	1969	Hatchback
VOLVO V40 Hatchback (525) T5 Lambda Sensor Diagnostic Probe Lambda Sensor Diagnostic Probe Lambda Sensor Diagnostic Probe	05.2014 - 08.2019	106280	180	245	1969	Hatchback
VOLVO V40 Hatchback (525) T5 Lambda Sensor Diagnostic Probe	05.2014 - 08.2019	106280	180	245	1969	Hatchback
VOLVO V40 Hatchback (525) T5 Drive-E Polestar Lambda Sensor Diagnostic Probe	05.2014 - 08.2019	138809	186	253	1969	Hatchback
VOLVO V40 Hatchback (525) T5 Drive-E Polestar Lambda Sensor Diagnostic Probe Lambda Sensor Diagnostic Probe Lambda Sensor Diagnostic Probe	05.2014 - 08.2019	138809	186	253	1969	Hatchback
VOLVO V60 I (155) 2.0 Polestar AWD Lambda Sensor Diagnostic Probe	06.2015 - 05.2018	120524	270	367	1969	Estate
VOLVO V60 I (155) T6 AWD Lambda Sensor Diagnostic Probe	10.2013 - 12.2018	117791	225	306	1969	Estate
VOLVO V60 I Cross Country (157) T5 Lambda Sensor Diagnostic Probe	03.2015 - 05.2018	147937	180	245	1969	Estate
VOLVO V60 I Cross Country (157) T5 Lambda Sensor Diagnostic Probe	03.2015 - 05.2018	147937	180	245	1969	Estate
VOLVO V60 I Cross Country (157) T5 AWD Lambda Sensor Diagnostic Probe	06.2016 - 05.2018	147938	180	245	1969	Estate
VOLVO V60 I Cross Country (157) T5 Drive-E Polestar AWD Lambda Sensor Diagnostic Probe	03.2015 - 07.2018	138816	186	253	1969	Estate
VOLVO V70 III (135) T4 Lambda Sensor Diagnostic Probe	03.2015 - 04.2016	113284	140	190	1969	Estate
VOLVO XC40 (536) T5 AWD Lambda Sensor Diagnostic Probe	10.2017 - 09.2021	128759	182	247	1969	SUV
VOLVO XC40 (536) T5 AWD Lambda Sensor Diagnostic Probe	10.2017 -	134183	184	250	1969	SUV
VOLVO XC40 (536) T5 AWD Lambda Sensor Diagnostic Probe	10.2017 -	134183	184	250	1969	SUV
VOLVO XC40 (536) T5 Polestar AWD Lambda Sensor Diagnostic Probe	10.2017 - 09.2019	138718	183	249	1969	SUV
VOLVO XC60 I SUV (156) T5 AWD Lambda Sensor Diagnostic Probe	10.2015 - 02.2017	119578	180	245	1969	SUV
VOLVO XC60 I SUV (156) T6 AWD Lambda Sensor Diagnostic Probe	10.2013 - 12.2017	117792	225	306	1969	SUV
VOLVO XC60 I SUV (156) T6 AWD Lambda Sensor Diagnostic Probe	10.2013 - 12.2017	117792	225	306	1969	SUV

OE information

Manufacturer	OE number	Reference information
VOLVO	31422309	
VOLVO	31460846	
VOLVO	31480731	
VOLVO	32225109	